

超微量工業安全實驗室 Ultra Trace Industrial Safety Hygiene

日期: 2010年11月19日

檢驗報告

報告編號: US/2010/B0134

權能國際國際股份有限公司

台北縣三重市興德路86號4樓

以下測試之樣品係由供應廠商所提供及確認:

產品名稱: ECOSPITAL 吸塵器

01 背景值

02 ECOSPITAL 吸塵器排氣口

送樣日期: 2010年11月10日 測試日期: 2010年11月11日

測試結果:

測試項目	CAS NO.	測試方法	測試結果		四人
			01	02	單位
Particle					
0.3 µm		本測試以無塵室內之空氣為進氣,測試吸塵 器排風口之微粒子數,以粒子數分析儀檢測	0	35	count/ft ³
0.5 µm		並記錄最大值。	0	32	count/ft ³
1 μm			0	28	count/ft ³

結論 : 參考ISO 14644 無塵室定義,此吸塵器不適合用於Class 1及Class 10以上之無塵室。

備註:1.本報告不得分離,分離使用無效。

- END -

Signed for and on behalf of

SGS Taiwan Ltd.

Anita Liao

Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試的樣品負責。本報告未經本公司書面許可,不可部份複製。

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms edocuments, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No. 136-1 Wu Kung Road, Wuku Industrial Zone, Taipei County, Taiwan. / 台北縣五股工業區五工路 136-1 號

SGS Taiwan Ltd.

t (886-2) 2299-3939 f (886-2) 2298-1338

www.tw.sgs.com

頁數:1 of 2



超微量工業安全實驗室 Ultra Trace Industrial Safety Hygiene

日期: 2010年11月19日

檢驗報告

報告編號: US/2010/B0134

權能國際國際股份有限公司

台北縣三重市興德路86號4樓

樣品照片



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試的樣品負責。本報告未經本公司書面許可,不可部份複製

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. No. 136-1 Wu Kung Road, Wuku Industrial Zone, Taipei County, Taiwan. / 台北縣五股工業區五工路 136-1 號

t (886-2) 2299-3939 f (886-2) 2298-1338 www.tw.sgs.com

頁數:2 of 2